


FIG.1




FIG.2




FIG.3



400 Construct the Spine
402 Affix the Struts
404 Lay the Tape Stack
406 Cast the Coil

FIG.4



500 Identify damaged coil
502 Heat coil assembly and remove infill
504 Heat specific solder joints
506 Extract the HTS tape stacks
508 Replace the HTS tape stacks
510 Recast the coil

FIG.5



602 Stellarator System
604 Plasma
606 Close-Fitting Coils
608 Blanket
610 Superconducting Coils
612 Power Supply
614 Cooling System
616 Diagnostic System
618 Control System

FIG. 6




FIG. 7