




FIG. 1

SCHEMATIC OF COMPOUNDING PROCESS EXAMPLE




FIG. 2

EXTRUDER BARREL AND SCREW CONFIGURATION EXAMPLE




FIG. 3