




Figure 1




Figure 2




Figure 3




Figure 4




Figure 5






Figure 6

**Figure 7**

Automatic Tool Changers for engaging the manufacturing base to the detachable process module for energising electrical and/or pneumatic connections so that no other wiring or tubing is required for electrical and/or pneumatic connections.

Figure 8




Figure 9




Figure 10




Figure 11




Figure 12





Figure 13

**Figure 14**




Figure 15




Figure 16




Figure 17




Figure 18




Figure 19




Figure 20




Figure 20A




Figure 21




Figure 22




Figure 23




Figure 24




Figure 25




Figure 26




Figure 27




Figure 28




Figure 29





Figure 30

Figure 31






Figure 32




Figure 33




Figure 34




Figure 35




Figure 36