




Fig. 1




Fig. 2A





Fig. 2B

4/6


Solder Ball Mount or printing process

Step 135



Saw singulation

Step 140



Step 145

Laser drilling solder mask




Fig. 2C




Fig. 3




Fig. 4A




Fig. 4B