

COATING A PERFORATED SURFACE

ABSTRACT

5 An example method of coating a surface includes rotating a sprayer about an axis and directing spray away from the axis using the sprayer. The method coats a surface with the spray. The method moves a fluid through apertures established in the surface to limit movement of spray into apertures. The apertures are configured to direct the fluid toward the axis.

10

Figure 1