

A METHOD OF BUILDING UP AN ALUMINUM ALLOY PART

The invention relates to a method of building up (i.e. repairing) an aluminum alloy part.

In general, a part is built up by providing material
5 (in the form of powder, frit, ...) at locations where the part presents cracks (or fissures) and/or depressions. To do this, it is common practice to use welding or brazing techniques.

The method of the invention can be used in
10 particular for building up a part of a turbomachine (e.g. a turbojet, a turboprop, a terrestrial gas turbine, ...) and, more particularly, a turbojet fan casing.

Turbojet fan casings are usually made of aluminum alloy and suffer damage during fabrication (blows from
15 tools) or while the turbojet is in operation (ingesting pebbles or other projectiles that strike the casing). In general, it is difficult to build up such casings by welding since the weldability of the aluminum alloys used is rather limited, such alloys having very high thermal
20 conductivity and great reflectivity.

Amongst known methods, it is known to build up a part by using tungsten inert gas (TIG) welding. Nevertheless, that method presents drawbacks: the zone of the part that is thermally affected by the welding is too
25 great and it presents significant amounts of deformation. Furthermore, before being able to proceed with building up, it is necessary to remove the fan casing so as to separate it from the remainder of the turbojet low-pressure compressor module (also known as the fan and
30 booster module), since the electric arc generated during TIG welding would damage ball bearings forming part of the assembly.

An object of the invention is to provide a method of building up a part by welding, which method gives rise to
35 a thermally affected zone that is limited and to deformations that are small in the build-up zone, and furthermore is capable of being used for building up a

turbojet fan casing without it being necessary to remove the casing.

To achieve this object, the invention provides a method of building up an aluminum alloy part by welding,
5 the method comprising the steps of:

- manually depositing a layer of aluminum alloy powder on the part in a build-up zone; and
- welding said powder layer onto said part by laser welding.

10 It has been found that the laser welding performed gives rise to a thermally affected zone and to deformations that are smaller than those that occur when performing TIG welding.

Furthermore, because the powder is deposited
15 manually, the equipment needed for implementing such a method is compact. This makes it easy to access the part that needs to be built up, even when it is still assembled with other parts. More particularly, this makes it possible to access a turbojet fan casing while
20 it is still integrated in the compressor module. Advantageously, the fan casing is thus built up without removing the casing from the remainder of the turbojet compressor module, thereby saving precious time. In addition, since no electric arc is generated by laser
25 welding, there is no risk of damaging ball bearings.

The invention and its advantages can be better understood on reading the following detailed description of implementations of the method of the invention. The description refers to the accompanying drawings, in
30 which:

- Figure 1 is a diagrammatic section view of an example of a part for building up;
- Figures 2 to 5 are diagrams showing various steps in an implementation of the method of the invention as ,
35 applied to the part of Figure 1;

- Figure 6 is a perspective view showing an example of a scraper used while implementing the method of the invention;

- Figure 7 is a diagrammatic perspective view showing an example of a part for building up, covered by a mask; and

- Figures 8 to 11 are diagrams showing the various steps in an implementation of the invention as applied to the Figure 7 part.

10 With reference to Figures 1 to 5, there follows a description of a first implementation of the method of the invention, used for filling in a cup-shaped depression 3 in a part 1, shown in section in Figure 1. The part 1 is a fan casing for a two-spool bypass turbojet, and it belongs to the low-pressure compressor module of the turbojet, which also comprises the fan and the low-pressure compressor (or booster).

15 The build-up zone 5 of the part 1 corresponds to the extent of the depression 3. Furthermore, when reference is made to the "surface" of the part, that term covers the general surface S of the part. In the build-up zone 5, the surface S therefore does not correspond to the bottom of the depression 3, but, as shown in dashed lines in Figure 1, to the surface S that the part would have if there were no depression 3.

20 In the method of the invention, a layer 8 of aluminum alloy powder 9 is deposited manually on the part 1, in the build-up zone 5.

25 In practice, to obtain the layer 8, it is possible to deposit at least two sublayers 11a, 11b in succession, each formed by a plurality of beads of powder 9, which beads are parallel and spaced apart at a pitch P.

30 In the example described, in order to build up (i.e. to repair) the part 1, the first sublayer 11a is deposited in the form of beads 12a that are spaced apart by a pitch P, and thereafter the second sublayer 11b is deposited that is made up of beads 12b spaced apart at

the same pitch P , but offset through a distance $P/2$ relative to the beads 12a.

Juxtaposing sublayers of beads of powder 9 makes it possible to obtain a layer 8 that is well densified, and
5 of thickness that is relatively stable.

In an implementation of the invention, the height H of the layer 8 of powder is calibrated relative to the surface S of the part 1. In this manner, the thickness E of the layer 8 for depositing is controlled, where the
10 thickness E has an influence on the quality of the laser welding that is performed. If the thickness were to be too small, then a lack of surface material would appear.

For a given depth D of depression (or crack) relative to the surface S of the part 1, the thickness E of the layer 8 is equal to $D+H$, where H is the height of
15 the layer 8 relative to the surface S of the part 1. By calibrating the height H , the thickness E is also controlled.

This calibration step naturally takes place after a step of depositing the layer of powder, and before the
20 step of laser welding.

To perform this calibration step, it is advantageous to make use of a scraper comprising at least one support foot that is caused to stand on the surface S of said
25 part, with a scraper blade set back relative to the stand so that the distance d between the scraper blade and the surface of said part corresponds to the height H that is desired for the layer 8 of powder.

An example scraper 13 is shown in Figures 3 and 6.
30 The scraper 13 stands on the horizontal surface S of the part 1 and includes a handle 17 that is connected to the scraper body 19. The body 19 has two support feet 21, one on either side (symmetrically about a vertical midplane of the scraper), and extending firstly
35 vertically downwards and then through a 90° bend so as to form two horizontal support strips 21a. When the scraper 19 is in use, it is these support strips 21a that are

caused to slide over the surface S. These support feet 21 define between them a broad notch 23 in a vertical plane. The scraper blade 25 is mounted on the body 19 and covers the notch 23 in part. This blade 25 is
5 suitable for sliding vertically relative to the body 19 so that it is possible to adjust the vertical position of the blade 25, and thus adjust the distance d between the scraper blade 25 and the surface S of the part 1, so that it corresponds to a determined value for the height H of
10 the layer of powder.

In the example, the blade 25 presents two oblong openings 27 that are vertically oriented, and the scraper has two screw-and-nut assemblies 29 that are fastened in the body 19 and through the openings 27.

15 In order to adjust the distance d and cause it to correspond with the height H, the screw-and-nut assemblies 29 are loosened, and the blade 25 is moved into the desired position, whereupon the assemblies 29 are re-tightened.

20 When the scraper 13 is in use, the support feet 21 are placed on either side of the layer 8 of powder (see Figure 3), the support strips 21a are pressed against the surface S, and the scraper is moved manually, causing its support strips to slide on the surface S. Because of the
25 support strips 21a, the orientation (here vertical orientation) of the blade 25 remains the same while the scraper 13 is being moved so that the distance d between the blade 25 and the surface S of the part 1 remains constant.

30 By passing the scraper 13 over the layer 8 of powder, as shown in Figure 3, the top portion of the layer 8 of powder is smoothed to a calibrated height H: the grains of powder 9 situated at a height greater than the height H are moved by the blade 25 towards the zones
35 of the layer 8 that are of a height that is less than the height H, or to the periphery of said layer 8.

After the layer 8 has been deposited, and advantageously calibrated in height, the laser welding step is performed.

For this step, use is made for example of a diode
5 layer 40 that provides beam/material interaction that is more regular than that provided by a laser of the yttrium aluminum garnet (YAG) type.

The laser beam 41 that is emitted then travels over the build-up zone 5, as shown in Figure 4. The energy
10 delivered by the beam 41 causes the powder 9 to melt and mix together with adjacent portions of the part 1. On cooling, the desired build up is obtained.

In one implementation, after the welding step, in order to restore aerodynamic properties to the part 1,
15 the part is leveled by machining in the build-up zone 5, since the surface of the part 1 in this zone is generally not perfectly plane after welding. Figure 5 shows the final part as obtained after the machining step.

With reference to Figures 7 to 12, there follows a
20 description of a second implementation of the build-up method of the invention. It differs from that of Figures 2 to 5 in that it makes use of a mask 30. The mask 30 is shown in perspective in Figure 7 and in section in Figure 8. By way of example, it is
25 constituted by a sheet of aluminum alloy.

The mask 30 is provided with an opening 32 of the same size as the build-up zone 5. The mask 30 is positioned on said part by making said opening 32 coincide with the build-up zone 5, and said layer 8 of
30 aluminum alloy powder is deposited in the build-up zone 5, overflowing onto the mask 30 (see Figure 9). The overlap zone is referenced 5a in Figures 9 and 11.

Then, the layer 8 is scraped and subjected to laser welding, as shown in Figures 10 and 11. These
35 steps are analogous to those described above and shown in Figures 3 and 4.

In the method of Figures 2 to 5, the periphery of the powder layer 8 corresponds substantially to that of the build-up zone 5, and the interaction between the laser beam 4 and the part 1 in the transition zone
5 between the build-up zone 5 and the remainder of the part 1 can lead to microcracks being formed. Such microcracks are harmful insofar as they are situated in the (near) periphery of the build-up zone 5, or even in the build-up zone 5, and they run the risk of weakening it.

10 By causing the layer 8 of powder to overlap onto the mask 30, the periphery of the layer 8 is offset to outside the periphery of the build-up zone 5. Should such microcracks be created during welding, then they are located at the periphery of the overlap zone 5a and are
15 therefore far enough away from the build-up zone 5 to avoid weakening it.

After the welding step, the mask 30 is removed together with the powder 9 of the overlap zone 5a that is welded onto the mask 30. Welded powder remains on the
20 part 1 only in the build-up zone 5. If necessary, the part can be leveled by machining in the build-up zone 5.

In the examples above, the part 1 may be made of aluminum alloy of type 6061, while the aluminum alloy powder 9 may be of type 5356 with grain size lying in the
25 range 63 micrometers (μm) to 125 μm , centered around 70 μm . In order to build up such a part 1 when it presents a depression having a maximum depth D equal to 0.75 millimeters (mm), the height H for the powder relative to the surface S is selected to be equal to
30 1.4 mm. The power of the laser diode 40 used is 2750 watts (W) so as to obtain good surface regularity in the build-up zone and so as to obtain a dilution zone of satisfactory depth. The dilution zone is the zone where mixing occurs between the filler material (i.e. the
35 powder 9) and the substrate (i.e. the part 1). It is desirable for the depth of the dilution zone not to be too great, and preferably it remains less than 0.05 mm.

The travel speed of the laser is 1 meter per minute (m/min). The mask 30 that is optionally used is made of a sheet of aluminum alloy of type 5182, having a thickness of 1.5 mm.

CLAIMS

1. A method of building up an aluminum alloy part by welding, the method being characterized by the steps of:

- manually depositing a layer of aluminum alloy powder on the part in a build-up zone;
- calibrating the height of the powder layer relative to the surface of said part; and
- welding said powder layer onto said part by laser welding.

10

2. A method according to claim 1, in which the height of the powder layer is calibrated by means of a scraper having at least one support foot that is caused to rest on the surface of said part, and a scraper blade that is set back relative to the support foot so that the distance between the scraper blade and the surface of said part corresponds to the height desired for the powder layer.

15

3. A method according to claim 2, in which the distance between the scraper blade and the surface of said part is adjustable, and in which said distance is adjusted so that it corresponds to the height desired for the powder layer.

20

4. A method according to any one of claims 1 to 3, in which, after the welding step, the part is leveled by machining in the build-up zone.

25

5. A method according to any one of claims 1 to 4, in which a mask is used that is provided with an opening having the same dimensions as the build-up zone, the mask being positioned on said part by causing said opening to correspond with the build-up zone, and said powder layer is deposited on the part in the build-up zone and overlaps onto said mask around said build-up zone.

30

35

6. A method according to claim 5, in which said mask is made of aluminum alloy sheet.

7. A method according to any one of claims 1 to 6, in
5 which said part is a turbomachine part.

8. A method according to claim 7, in which said part is a turbojet fan casing.

10 9. A method according to claim 8, in which said fan casing is built up without removing said casing from the remainder of the low pressure compressor module of the turbojet.