




Figure 1




Figure 2




Figure 3




Figure 4




Figure 5




Figure 6




Figure 7




Figure 8

Recalibration of the below digital twin is triggered.

Name: HEX Digital Twin

Trigger Date: 5th August 2021 11:00 AM SGT

Affected Instruments:

Instrument Name	Minimum	Mean	Median	St. Deviation	Maximum	Current Soft-tag value	Deviation
Instrument 1	20	30	32	3	38	36	4.75%
Instrument 2	200	300	320	30	380	350	9.00%

Affected Equipment: HE-0001

Bad Sensor Data: No

Occurence of Historical New Normal: No

Actions Suggested: inspect affected equipment to approve or decline recalibration.

Performance Assessment:




Figure 9