






[FIG. 1]

Comparison results of carbon falling-off (transfer)



[Confirmation method]

A waste cloth is rubbed against a slit surface and carbon transfer is confirmed with a microscope



[FIG. 2]

Comparison results of open state of sprocket hole

