



Fig. 2 Prior Art




Fig. 1 Prior Art




FIG. 3





Fig. 4






Fig. 6





Fig. 7



Drainage holes 60

62

58

52

56

Top view




Fig. 9

Bottom




Fig. 10






Fig. 12







Fig. 13

Fig. 14






Fig. 15




Fig. 16




Fig. 17A

Venturi side view




Fig. 17B




Fig. 18




Fig. 19





Fig. 20






Fig. 22A




Fig. 22B




Fig. 22C




Fig. 23




Fig. 24




Fig. 25




Fig. 26




Fig. 27




Fig. 28





Fig. 29A






Fig. 29C




Fig. 30




Fig. 31A




Fig. 31B








Fig. 32












Fig. 37





Fig. 38

Fig. 39






Fig. 40





Fig. 41






Fig. 42




Fig. 43





Fig. 44






Fig. 46




Fig. 47




FIG. 48




Fig. 49




Fig. 50




Fig. 51A




Fig. 51B




Fig. 51C




Fig. 51D




Fig. 52




Fig. 53C




Fig. 53B




Fig. 53A






Fig. 56A

Fig. 56B



798




Fig. 56C

Fig. 56D




Fig. 57




Fig. 58




Fig. 59




Fig. 61




Fig. 60




Fig. 62




Fig. 63




Fig. 65




Fig. 64

Fig. 67

920
710





Fig. 66

920

900






Fig 71





Fig. 70






Fig. 73

Pupa tray, and
cartridge is
approaching the
pupa tray




Fig. 72

Pupa tray,
and cartridge
inside water
(door open)