

FIG. 1A




FIG. 1B





FIG. 1C


FIG.2A



HEAVE (FLATNESS)



FIG.2B



WAVINESS



FIG.2C



MICROWAVINESS



FIG.2D

ROUGHNESS
(ARITHMETIC AVERAGE)
(ROUGHNESS Ra)




FIG.3




FIG.4








FIG. 5A

FIG. 5B

FIG. 5C





FIG. 6A

FIG. 6B

FIG. 6.




FIG. 7D

FIG. 7C

FIG. 7B

FIG. 7A









FIG. 8A

FIG. 8B

FIG. 8C




FIG. 9A




FIG. 9B