

ABSTRACT

When removing magnetic disks and spacers from a hard disk drive apparatus, as necessary, during the assembly of the hard disk drive apparatus,
5 in order to suppress the occurrence of removal failures when removing the spacers using a gripping jig, a surface roughness Rz of an outer circumferential edge surface of a spacer is set to be at least 1.5 μm .