




FIG.1




FIG. 2




FIG. 3




FIG. 4




FIG.5




FIG. 6




FIG. 7




FIG. 8


|   | Marks                                                                                               | Outputs of sensors       |
|---|-----------------------------------------------------------------------------------------------------|--------------------------|
| 1 | <br>Blank<br>Blank | 320 OFF<br>321 OFF       |
| 2 | <br>Blank<br>Mark  | 320 OFF<br>321 ON OFF    |
| 3 | <br>Mark<br>Blank | 320 ON OFF<br>321 OFF    |
| 4 | <br>Mark<br>Mark | 320 ON OFF<br>321 ON OFF |

FIG.9




FIG.10