




FIG. 2




FIG. 3




FIG. 4A




FIG. 4B




FIG. 5A




FIG. 5B




FIG. 6

Recipe step setting					
No.	Recipe steps	Instructed APC	Pressure command	Valve of bypass line	Valve of exhaust line
1	APC1 slow exhaust	APC1	SLOW VAC	OPEN	CLOSE
2	APC1 Press	APC1	PRESS	↓	↓
3	APC1 slow exhaust (2nd stage)	APC1	SLOW VAC	↓	↓
4	LEAK CHECK	APC1	FULL CLOSE	CLOSE	↓
5	APC2 Full Open	APC2	FULL OPEN	↓	OPEN
6	APC2 Press	APC2	PRESS	↓	↓
7	APC2 Full Close	APC2	FULL CLOSE	↓	CLOSE



: APC not subjected to control is closed

FIG. 7

