

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5

	ABERRATION (μm)	0.00D	+0.50D	+1.00D
EXAMPLE 1	$C_3^{-1} : 0.24\mu\text{m}$ $C_4^0 : 0.33\mu\text{m}$			
EXAMPLE 2	$C_3^{-1} : 0.24\mu\text{m}$ $C_4^0 : 0.29\mu\text{m}$			
EXAMPLE 3	$C_3^{-1} : 0.24\mu\text{m}$ $C_4^0 : 0.24\mu\text{m}$			
EXAMPLE 4	$C_3^{-1} : 0.24\mu\text{m}$ $C_4^0 : 0.19\mu\text{m}$			
EXAMPLE 5	$C_3^{-1} : 0.24\mu\text{m}$ $C_4^0 : 0.13\mu\text{m}$			
COMPARA- TIVE EXAMPLE 1	$C_3^{-1} : 0.24\mu\text{m}$ $C_4^0 : \text{zero}$			

FIG.6

	ABERRATION (μm)	0.00D	+0.50D	+1.00D
EXAMPLE 6	$C_3^{-1} : 0.14\mu\text{m}$ $C_4^0 : 0.23\mu\text{m}$			
EXAMPLE 7	$C_3^{-1} : 0.14\mu\text{m}$ $C_4^0 : 0.13\mu\text{m}$			
EXAMPLE 8	$C_3^{-1} : 0.14\mu\text{m}$ $C_4^0 : 0.03\mu\text{m}$			
COMPARA- TIVE EXAMPLE 2	$C_3^{-1} : 0.14\mu\text{m}$ $C_4^0 : \text{zero}$			