




FIG.1




FIG.2




FIG.3




FIG.4




FIG. 5




FIG. 6a




FIG. 6b





FIG. 6c






Fig. 8




Fig. 9





Fig. 10






Fig. 16a




Fig. 16b

F	H	J	G
50	50	25	17
80	80	34	22
100	100	45	32
150	150	55	36

Fig. 16c




Fig. 15a




Fig. 15b

F	H	J	G
50	25	25	17
80	40	34	22
100	50	45	32
150	75	55	36

Fig. 15c




Fig. 14a




Fig. 14b

F	H	J	G
50	50-25	25	17
80	80-40	34	22
100	100-50	45	32
150	150-75	55	36

Fig. 14c




Fig. 13a





Fig. 13b


F	H	J	G
50	50	25	17
80	80	34	22
100	100	45	32
150	150	55	36

Fig. 13c



F	H	J	G
50	50	25	17
80	80	34	22
100	100	45	32
150	150	55	36

Fig. 12c



F	H	J	G
50	50	25	17
80	80	34	22
100	100	45	32
150	150	55	36

Fig. 17c




Fig. 18