

METHOD OF MANUFACTURING LOW CONTAMINANT WIPER

Abstract of the Disclosure

A method of manufacturing a polyester textile fabric having a relatively low level of particulate contaminants and high absorbency is provided by heatsetting the fabric at a temperature of 300° F or less.

Figure 1