




FIG. 1




FIG. 2

3/79




FIG. 3




FIG. 4




FIG. 5




FIG. 6

5/79




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16

106




FIG. 17

10/79




FIG. 18

1179




FIG. 19

12/79




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29

21/79




FIG. 30




FIG. 31




FIG. 32




FIG. 33

23/79




FIG. 34

24/79




FIG. 35

25/79




FIG. 36

26/79




FIG. 37

27179




FIG. 38




FIG. 39

28/79




FIG. 40




FIG. 41

29/79




FIG. 42




FIG. 43




FIG. 44




FIG. 45

31/79




FIG. 46




FIG. 47

32/79




FIG. 48




FIG. 49




FIG. 50

34/79




FIG. 51

35/79




FIG. 52




FIG. 53

36/79




FIG. 54




FIG. 55

38/79




FIG. 56

39/79




FIG. 57

40/79




FIG. 58

41/79




FIG. 59




FIG. 60




FIG. 61

43/79




FIG. 62

44/79




FIG. 63




FIG. 64




FIG. 65




FIG. 66




FIG. 67




FIG. 68




FIG. 69




FIG. 70




FIG. 71

49/79




FIG. 72

50/79




FIG. 73

51/79




FIG. 74




FIG. 75




FIG. 76

53/79




FIG. 77

54/79




FIG. 78




FIG. 79




FIG. 80




FIG. 81




FIG. 82




FIG. 83




FIG. 84




FIG. 85




FIG. 86

59/79




FIG. 87




FIG. 88




FIG. 89

61/79




FIG. 90

62/79




FIG. 91




FIG. 92




FIG. 93




FIG. 94




FIG. 95




FIG. 96

66/79




FIG. 97




FIG. 98




FIG. 99




FIG. 100




FIG. 101





FIG. 102



70/79




FIG. 105




FIG. 104

71/79




FIG. 106




FIG. 107

72/79




FIG. 108

73/79




FIG. 109

74/79




FIG. 110





FIG. 112






FIG. 113




FIG. 114




FIG. 115




FIG. 117

FIG. 116

78/79




FIG. 117A

