




FIG.1




FIG. 2




FIG.3




FIG. 4




FIG.5




FIG. 7




FIG. 8


	Marks	Outputs of sensors
1	 Blank Blank	320 OFF 321 OFF
2	 Blank Mark	320 OFF 321 ON OFF
3	 Mark Blank	320 ON OFF 321 OFF
4	 Mark Mark	320 ON OFF 321 ON OFF

FIG.9




FIG.10