





FIG.1




FIG. 2




FIG.3




FIG.4




FIG.5




FIG. 6




FIG. 7




FIG.8




	Marks	Outputs of sensors
1		320 OFF 321 OFF
2		320 OFF 321 ON OFF
3		320 ON OFF 321 OFF
4		320 ON OFF 321 ON OFF

FIG.9




FIG.10