



[Fig. 1]




[Fig. 3]




[Fig. 4]

Combination	Arrangement of marking	Outputs of sensors
1	 Blank Blank	21 OFF 21 OFF
2	 Blank M	21 OFF 21 ON OFF
3	 M Blank	21 ON OFF 21 OFF
4	 M M	21 ON OFF 21 ON OFF


[Fig. 5]




[Fig. 7]




[Fig. 8]




[Fig. 9]




[Fig. 10]




[Fig. 11]



[Fig. 12]



[Fig. 13]



[Fig. 14]

