

1/16




FIG. 1A

2/16




FIG. 1B

3/16




FIG. 2A




FIG. 2B

SUBSTITUTE SHEET (RULE 26)

5/16




FIG. 2C

6/16




FIG. 3

7/16





FIG. 4A

8/16



SUBSTITUTE SHEET (RULE 26)

9/16





FIG. 5

10/16



SUBSTITUTE SHEET (RULE 26)

11/16




FIG. 6B

12/16




FIG. 6C

This exploded perspective view illustrates the assembly of a mechanical device. The components are labeled with reference numerals: 519, 518, 519, 520, 544d, 545b, 544c, 543b, 610b, 610a, 750, 640, 610c, 525, 515, 516, 610f, 511, 522, 622, 510, 670, 772, 770, 610d, 610e, 650, and 515. The diagram shows how these parts, including a long shaft (515), a handle (516), and various brackets and pins, fit together to form the complete assembly.

FIG. 7

SUBSTITUTE SHEET (RULE 26)




FIG. 8A




FIG. 8B

16/16




FIG. 9