




Figure 1 : Measurement of contact angles

5




Figure 2 : Contact angles values




Figure 3 : Surface energies determined by the Owens-Wendt method