

1/8




FIG. 1




FIG. 2(a)




FIG. 2(b)




FIG. 2(c)




FIG. 3(a)




FIG. 3(b)




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8

Max EHT-MCS for 1 SS	Max EHT-MCS for 2 SS	Max EHT-MCS for 3 SS	Max EHT-MCS for 4 SS	Max EHT-MCS for 5 SS	Max EHT-MCS for 6 SS	Max EHT-MCS for 7 SS	Max EHT-MCS for 8 SS
Max EHT-MCS for 9 SS	Max EHT-MCS for 10 SS	Max EHT-MCS for 11 SS	Max EHT-MCS for 12 SS	Max EHT-MCS for 13 SS	Max EHT-MCS for 14 SS	Max EHT-MCS for 15 SS	Max EHT-MCS for 16 SS

FIG. 9




FIG. 10




FIG. 11