

FIG.1




FIG.2A




FIG.2B




FIG.3




FIG.4A




FIG.4B




FIG.5A




FIG.5B




FIG.6




FIG. 7A




FIG. 7B




FIG.8A




FIG.8B




FIG.9




FIG.10




FIG.11




FIG.12A





FIG.12B



$$Vr = \frac{V2}{V1} \times 100$$

FIG.13A




FIG.13B





FIG.14



$$RSm = \frac{1}{N} \sum_{i=1}^N RSm_i$$

FIG.15

