




Figure 1




Figure 2




Figure 3




Figure 4




Figure 5




Figure 6







Figure 7



Automatic Tool Changers for engaging the manufacturing base to the detachable process module for energising electrical and/or pneumatic connections so that no other wiring or tubing is required for electrical and/or pneumatic connections.

Figure 8






Figure 11




Figure 12








Figure 13

**Figure 14**






Figure 18




Figure 19




Figure 20




Figure 20A




Figure 21




Figure 22




Figure 23




Figure 24




Figure 25




Figure 26




Figure 27




Figure 28




Figure 29






Figure 30

Figure 31



**Figure 32**




Figure 33




Figure 34




Figure 35




Figure 36