

FIG. 1




FIG. 2




FIG. 3

$H \cdot R =$

	C1	C2	...	C128	C129	C130	...	C136
R1	h11	h12	...	h1128	1	0	...	0
R2	h21	h22	...	h2128	0	1	...	0
.	.	.	.	.	.	.	.	.
.	.	.	.	.	.	.	.	.
.	.	.	.	.	.	.	.	.
R8	h81	h82	...	h8128	0	0	...	1

$\cdot$

r1
r2
.
.
.
r128
P21
P22
.
.
P28

$=$

0
0
.
.
.
0

FIG. 4




FIG. 5

$$H' \cdot R' =$$

	C1'	C2'	...	C136'
R1'	h11'	h12'	...	h1136'
R2'	h21'	h22'	...	h2136'
...	...	...	...	...
R8'	h81'	h82'	...	h8136'

$$\cdot \begin{bmatrix} r1' \\ r2' \\ \vdots \\ r128' \\ P1' \\ P2' \\ \vdots \\ P8' \end{bmatrix} = \begin{bmatrix} S1 \\ S2 \\ \vdots \\ S8 \end{bmatrix}$$

FIG. 6




FIG. 7




FIG. 8




FIG. 9

$$H'' \cdot R'' =$$

	$C1''$	$C2''$	$\cdot$	$\cdot$	$\cdot$	$C128''$
$R1''$	$h11''$	$h12''$	$\cdot$	$\cdot$	$\cdot$	$h1128''$
$R2''$	$h21''$	$h22''$	$\cdot$	$\cdot$	$\cdot$	$h2128''$
$\cdot$	$\cdot$	$\cdot$	$\cdot$	$\cdot$	$\cdot$	$\cdot$
$\cdot$	$\cdot$	$\cdot$	$\cdot$	$\cdot$	$\cdot$	$\cdot$
$\cdot$	$\cdot$	$\cdot$	$\cdot$	$\cdot$	$\cdot$	$\cdot$
$R8''$	$h81''$	$h82''$	$\cdot$	$\cdot$	$\cdot$	$h8128''$

$$\cdot \begin{bmatrix} r1'' \\ r2'' \\ \vdots \\ r128'' \end{bmatrix} = \begin{bmatrix} S1'' \\ S2'' \\ \vdots \\ S8'' \end{bmatrix}$$

FIG. 10




FIG. 11

