



INTERNATIONAL APPLICATION PUBLISHED UNDER THE PATENT COOPERATION TREATY (PCT)

(51) International Patent Classification ⁷ : B23P 15/00	A1	(11) International Publication Number: WO 00/44525 (43) International Publication Date: 3 August 2000 (03.08.00)
(21) International Application Number: PCT/US99/28819 (22) International Filing Date: 3 December 1999 (03.12.99) (30) Priority Data: 09/239,263 29 January 1999 (29.01.99) US (71) Applicant: CHROMALLOY GAS TURBINE CORPORATION [US/US]; 4430 Director Drive, San Antonio, TX 78219 (US). (72) Inventors: JOHNSON, Bruce; 229 Antiqua Way, Niceville, FL 32578 (US). BLUMANSTOCK, Ben; 2305 Valley Place, Navarre, FL 32566 (US). (74) Agent: BITTMAN, Mitchell, D.; Sequa Corporation, 3 University Plaza, Hackensack, NJ 07601 (US).	(81) Designated States: AE, AL, AM, AT, AU, AZ, BA, BB, BG, BR, BY, CA, CH, CN, CR, CU, CZ, DE, DK, DM, EE, ES, FI, GB, GD, GE, GH, GM, HR, HU, ID, IL, IN, IS, JP, KE, KG, KP, KR, KZ, LC, LK, LR, LS, LT, LU, LV, MA, MD, MG, MK, MN, MW, MX, NO, NZ, PL, PT, RO, RU, SD, SE, SG, SI, SK, SL, TJ, TM, TR, TT, TZ, UA, UG, UZ, VN, YU, ZA, ZW, ARIPO patent (GH, GM, KE, LS, MW, SD, SL, SZ, TZ, UG, ZW), Eurasian patent (AM, AZ, BY, KG, KZ, MD, RU, TJ, TM), European patent (AT, BE, CH, CY, DE, DK, ES, FI, FR, GB, GR, IE, IT, LU, MC, NL, PT, SE), OAPI patent (BF, BJ, CF, CG, CI, CM, GA, GN, GW, ML, MR, NE, SN, TD, TG). Published With international search report. Before the expiration of the time limit for amending the claims and to be republished in the event of the receipt of amendments. *G00001*	

(54) Title: REPAIR OF TURBINE EXHAUST CASE

(57) Abstract

A process is provided for repairing the horizontal mount area of a JT9D turbine exhaust case (1) having two mounting flanges (2, 3) by inspecting the horizontal mount area, weld repairing any defects found in the case wall and installing a reinforcement brace onto the inside of the case wall in the horizontal mount area, wherein the reinforcement brace overlaps the area under the second mounting flange.

