




FIG. 1




FIG. 2

$$H =$$

c_1	c_2	c_3	c_4	c_5	c_6	c_7	c_8	c_9	c_{10}	c_{11}	c_{12}
0	0	1	0	0	1	1	1	0	0	0	0
1	1	0	0	1	0	0	0	0	0	0	1
0	0	0	1	0	0	0	0	1	1	1	0
0	1	0	0	0	1	1	0	0	1	0	0
1	0	1	0	0	0	0	1	0	0	1	0
0	0	0	1	1	0	0	0	1	0	0	1
1	0	0	1	1	0	1	0	0	0	0	0
0	0	0	1	1	0	0	0	1	0	0	1
1	0	0	1	1	0	1	0	0	0	0	0
0	0	0	0	0	1	0	1	0	0	1	1
0	1	1	0	0	0	0	0	1	1	0	0

FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8






FIG. 9


10/12

**FIG. 10**

11/12

**FIG. 11**

12/12

**FIG. 12**