

METHOD FOR REMOVING AN ALUMINIDE COATING FROM A SUBSTRATE

ABSTRACT

5 A method for removing an aluminide coating from a
substrate includes the steps of contacting the surface of the substrate
with at least one stripping composition to degrade the coating. The
stripping composition includes an aliphatic or aromatic sulfonic acid,
and at least one additive. The coating is then removed.

10

Figure 3