

A B S T R A C T

PROCESS FOR THE CONVERSION OF A FEEDSTOCK  
COMPRISING LINEAR OLEFINS

Process for the conversion of a feedstock comprising linear olefins into a product enriched in branched olefins, which process comprises contacting the feedstock with a tectometallosilicate having a ferrierite crystal structure at an olefin partial pressure of less than or equal to 0.5 bar.