




FIG. 1





FIG. 2



Surface
normal
[101]

a-axis [100]

c-axis [001]

FIG. 3b

FIG. 3a

Pt
●
Fe
●




FIG. 4




FIG. 5a




FIG. 5b




FIG. 5c




FIG. 6b




FIG. 6a




FIG. 7