NUCLEATION-FREE GAP FILL ALD PROCESS

ABSTRACT

Processing methods comprise forming a gap fill layer comprising tungsten or molybdenum by exposing a substrate surface having at least one feature thereon sequentially to a metal precursor and a reducing agent comprising hydrogen to form the gap fill layer in the feature, wherein there is not a nucleation layer between the substrate surface and the gap fill layer.

(fig. 6)