ABSTRACT

INTEGRATED CIRCUIT SYSTEM EMPLOYING BACKSIDE ENERGY SOURCE FOR ELECTRICAL CONTACT FORMATION

A method for manufacturing an integrated circuit system includes: providing a first material; forming a second material over a first side of the first material; and exposing a second side of the first material to an energy source to form an electrical contact at an interface of the first material and the second material.

Fig. 1