




FIG. 1A




FIG. 1B




FIG. 1C




FIG. 2A




FIG. 2B




FIG. 2C




FIG. 2D




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D

10/23




FIG. 3E




FIG. 3F




FIG. 4




FIG. 5A

SiC resistivity for each first, second direction in area of 2 to 25 Ωcm

Normal distribution




FIG. 5B

SiC resistivity for each first, second direction in area of 1 Ωcm

Normal distribution




FIG. 5C

SiC resistivity for each first, second direction in area of 1 Ωcm or less

Normal distribution




FIG. 5D

Change in hardness in first direction, second direction

Normal distribution




FIG. 6




FIG. 7




FIG. 8A




FIG. 8B




FIG. 9A




FIG. 9B




FIG. 10A




FIG. 10B




FIG. 11A




FIG. 11B




FIG. 12A




FIG. 12B




FIG. 13A




FIG. 13B




FIG. 14




FIG. 15