




1/17

**FIG. 1**

2/17



3/17






FIG. 4A




FIG. 4B




FIG. 5




FIG. 6A

HARQ Transmission




FIG. 6B

8/17

710 ↗





FIG. 7A




FIG. 7B

9/17

810





FIG. 8A

HARQ Transmission




FIG. 8B

10/17

910





FIG. 9A







FIG. 9B

11/17


**FIG. 10**

12/17


**FIG. 11**

**FIG. 12**


14/17

**FIG. 13**


15/17

**FIG. 14**

16/17

**FIG. 15**

17/17

**FIG. 16**