

FIG. 1A




FIG. 1B




FIG. 2




FIG. 3

1




FIG. 4




FIG. 5

1A





FIG. 6

FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11

1B




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17

1B




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31

1E




FIG. 32




FIG. 33






FIG.34A



POWER FACTOR=1 OF LOAD

FIG.34B



POWER FACTOR $\neq$ 1 OF LOAD

FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39






FIG. 40*FIG. 41*

FIG. 42




FIG. 43




FIG. 44



FIG. 45
(PRIOR ART)

