Process for the Production of Epoxides from Olefins

Abstract

Process for the production of epoxides from olefins and hydrogen peroxide in the presence of a zeolite containing titanium atoms as catalyst, to which neutral- or acid-reactive salts are added before or during the reaction.

FIG. 2