

FIG. 1A




FIG. 1B






FIG. 1C

FIG.2A




HEAVE (FLATNESS)

FIG.2B



WAVINESS

FIG.2C





MICROWAVINESS

FIG.2D



ROUGHNESS
(ARITHMETIC AVERAGE)
(ROUGHNESS Ra)

**FIG.3**

**FIG.4**








FIG. 5C

FIG. 5B

FIG. 5A





FIG. 6A

FIG. 6B

FIG. 6C




FIG. 7D

FIG. 7C

FIG. 7B

FIG. 7A








FIG.8C

FIG.8B

FIG.8A




FIG. 9A




FIG. 9B




FIG.10




FIG.11A



FIG.11B



FIG.11C



FIG.11D