

1/7




FIG. 1




FIG. 2A

2/7




FIG. 2B




FIG. 3




FIG. 4

3/7




FIG. 5





FIG. 6

Copper Oxide removal by Ontos

**FIG. 7**




FIG. 8A




FIG. 8B




FIG. 8C





FIG. 8D

**FIG. 9**




FIG. 10A




FIG. 10B




FIG. 10C