

5

Abstract

A production method for fine metal particles includes a step of preparing metal particles and a step of supplying the metal particles with a feed gas containing a hydrocarbon, wherein the contact between the feed gas and the metal particles is carried out at a temperature of 600°C to 900°C.

10