

ABSTRACT OF THE DISCLOSURE

CATHODIC ARC VAPOR DEPOSITION COATINGS FOR DIMENSIONAL RESTORATION OF SURFACES

A process for repairing a workpiece includes the steps of: providing a workpiece having at least one interior surface requiring restoration; providing a source of repair material; and depositing the repair material onto the at least one interior surface using a technique which is a near non-line of sight technique.

Fig. 1