




[FIG. 1]




[FIG. 2]




[FIG. 3]




[FIG. 4]




[FIG. 5]




[FIG. 6]




[FIG. 7]



[FIG. 8]




[FIG. 9]




[FIG. 10]

		Gw (mm)							
		1	2	3	4	5	6	7	8
G (mm)	3	B	B	A	A+	A+	A+	A+	A+
	4	B	B	A-	A	A+	A+	A+	A+
	5	B	B	B	B	A	A+	A+	A+
	6	B	B	B	B	A-	A	A+	A+


[FIG. 12]




[FIG. 13]




[FIG. 14]



[FIG. 15]



[FIG. 16]



[FIG. 17]

