

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5A




FIG. 5B




FIG. 6A




FIG. 6B




FIG. 7




FIG. 8




FIG. 9A




FIG. 9B




FIG. 9C




FIG. 10




FIG. 11

	Failing Cell						
	MC11	MC21	MC31	MC41	MC51	MC61	MC71
PDS1	0	1	0	1	1	1	1
PDS2	0	0	1	0	1	1	1
CR	0	1	1	1	0	0	0
FBN	3						

FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18A




FIG. 18B




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25

