




FIG. 1A
(PRIOR ART)




FIG. 1B
(PRIOR ART)




FIG. 1C
(PRIOR ART)




FIG. 1D
(PRIOR ART)




FIG. 1E
(PRIOR ART)




FIG. 1F
(PRIOR ART)




FIG. 2A




FIG. 2B




FIG. 2C




FIG. 2D




FIG. 2E




FIG. 2F




FIG. 2G




FIG. 2H




FIG. 2I




FIG. 2J




FIG. 2K

9/26




FIG. 2L




FIG. 2M




FIG. 3A




FIG. 3B




FIG. 3C

12/26

SOLDER JOINT CAN NOT BE INSPECTED




FIG. 4A



SOLDER JOINT CAN BE INSPECTED






FIG. 4B










FIG. 6A






FIG. 6D




FIG. 6E




FIG. 6F




FIG. 7A




FIG. 7B




FIG. 7C






FIG. 7D






FIG. 8D




FIG. 8C




FIG. 9A




FIG. 9B




FIG. 9C




FIG. 9D




FIG. 9E




FIG. 9F