




[圖1]




[図2]



[図3]



[図4]



[図5]






FIG. 1 is a schematic diagram of a mechanical assembly in a cross-sectional view. The assembly includes a base 10, a moving part 20, and a guide 30. A roller 40 is mounted on the moving part 20, which is guided by a track 31. A spring 50 is connected to the moving part 20 and the base 10. A coordinate system (X, Y, Z) is shown at the bottom right. Dimensions MV and SL are indicated. Arrows indicate movement directions.


[図7]




[図8]



[図9]




[図10]







[図12]




[図13]



[図14]



[図15]



[図16]

