

ABSTRACT

GETTERING LAYER FORMING METHOD

A gettering layer forming method includes a coating step of applying a solution of metal salt to a back side of a wafer, and a drying step of drying the wafer after performing the coating step, thereby forming a gettering layer containing the metal salt on the back side of the wafer.

(Figure 3A)