

ABSTRACT OF THE DISCLOSURE

An expanded non-bonded mesh well screen. A method of manufacturing a well screen includes the steps of: expanding
5 at least a portion of a screen jacket; and then securing the screen jacket onto a base pipe. A well screen system includes a base pipe and an at least partially expanded screen jacket surrounding the base pipe. The screen jacket is expanded prior to being positioned on the base pipe.

10