


100








FIG. 2


(a) AFTER SEALING
WITH RESIN




(b) AFTER REMOVING FIRST
UNNECESSARY RESIN



(c) BEFORE REVERSING
TOPSIDE DOWN



(d) AFTER REVERSING
TOPSIDE DOWN



(e) REMOVAL OF SECOND
UNNECESSARY RESIN




FIG. 3




FIG. 4




FIG. 5






FIG. 6



(a) BEFORE REVERSING
TOPSIDE DOWN



(b) AFTER REVERSING
TOPSIDE DOWN




FIG. 7





FIG. 8

(a) BEFORE
RE-REVERSING



(b) AFTER
RE-REVERSING




FIG. 9