




[Fig. 1]




[Fig. 2]




[Fig. 3]




[Fig. 4A]




[Fig. 4C]




[Fig. 5]




[Fig. 6]




[Fig. 7]




[Fig. 8]





[Fig. 9]




[Fig. 10]

Combination	Arrangement of marking	Outputs of sensors
1	 Blank Blank	OFF OFF
2	 Blank M	OFF ON
3	 M Blank	ON OFF
4	 M M	ON ON


[Fig. 11]




[Fig. 12]




[Fig. 13]




[Fig. 14]



[Fig. 17]



[Fig. 18]



[Fig. 19]

