

Fig.1




Fig.2




Fig.3




Fig.4




Fig.5




Fig.6




Fig.7






Fig.8

(a)



(b)



B-B SECTION

This diagram shows an exploded perspective view of a mechanical assembly. The components are numbered as follows: 4, 5, 8, 10, 11, 15, 16, 17, 22, 24, 26, 27, 31, 35, 37, 39, 42, 43, 45, 47, 48, 49, 50, 58, and 60. The assembly includes a motor (24) with a gear (22) and a series of gears (16, 11, 8, 17) connected by a shaft (15). A bracket (47) holds components 48, 49, and 50. A spring (37) is also visible. Orientation labels include 'TOP' at the top, 'BOTTOM' at the bottom, 'Left' on the right side, and an arrow labeled '4' pointing towards the top right.

Fig.10




Fig.11




Fig.12




Fig.13




Fig.14




Fig.15






Fig.16

(a)



(b)



(c)




Fig.17

